EQUINE DENTAL RECORD

Date 5-1-16

Owner: John Doe Phone: (123) 456-6789 Cell Phone

Address: 123 Random Dr. City: Mason State: MI Zip: 48854

Equine Name: Ivy Age: 11yr Sex: Male / MC / (Female)

Breed: Paint Color: Blk/Wht. Condition: 1 2 3 4 5 6 7 8 9

Use: *Pleasure* *Performance* *Racing* (*Other*) Bit: *Snaffle*/ Feed: Graze / Hay / Processed



HISTORY/COMMENTS: Maintenance - reduced Stepped 110/210 - ulcers and sharp pts reduced on buccal & lingual areas - abrasions present - reduced bulbed rostral 106/206 - reduced 308/309 408/409 waves - damage to 109/209 cupped - reduced 311 caudal ramp Horse is a cribber - cleaned up chips on incisors

VITALS: WNL HR: WNL /RSP: WNL /OVERALL WELLNESS:

VETERINARIAN: FILLED IN BY Attending Vet with contact info

SEDATION USED: FILLED IN BY Attending Vet

INCISORS		CANINES	WOLF TEETH	PREMOLARS/MOLARS	
___Ventral Curve	___Realign	___Cut	___Extract	X Float	X Stepped
___Dorsal Curve	___Reduction	___Buff	___Upper	X Bitseat	X Sharp Points
___DGL 3	___Angle Change	___Remove Tarter	___Lower	X Reduced	___Caps
___DGL 4	___Extract	___Elevate	___Anterior	___Balance	___Cap Fragments
___Caps	___Missing	___Blind	___Lingual	___Extract	___Impacted
___Cap Fragments	X Other	___Fracture	___Buccal	___ETR	___Supernumerary
___Supernumerary	Chips on upper incisors	___Abnormal	___Fragment	X Hooks	___Expired
___Overjet/Overbite		X None	___Blind	X Ramps	___Fractured
___Underjet/Underbite		___Other	X Other none	X Wave	___Mobile
___Abnormal				___Protuberant	